






WOLVERTON BUILDING








HELIOS PARK





Notes

- Initially 6 solar panels will be installed, with room to expand to 8.
 The human sundial is to be constructed of pervious pavers, or colored pervious concrete, to help minimize site runoff.
- The dry laid stream to be constructed with river stone, or recycled colored crushed glass.
- The existing privacy fence to be screened with a climbing flowering vine or espaliered flowering trees.
- Sidewalk murals to be painted using volunteer labor, such as local school children or boy scouts.
- New ADA-compliant handrails are to be installed on the existing

Legend

- LED Accent Lighting
- LED Pathway Lights
- Trash Receptacle
 The Snyder Building
- (Juergen's Hardware)
 2. Solar Trees w/ Native
 Timber
- 3. Stone Maintenance Access
- 4. Dry Laid Creek Bed
- Interpretive Sign for Human Sundial
- Open Grass Play Area
- Seasonal Plantings (Annuals)
- Perennial Flowers
- Landscaping Trellis or Espaliered Shrubs
- 10. Park Benches (typ.)
- Human Sundial in Pervious Pavers or Colored Concrete
- Rain Garden Interpretive Sign
- 13. Rain Garden Plantings
- 14. Shrub Row
- 15. Sidewalk Murals
- 16. Shrub Massing
- Smartmeter, Panel Box & Interpretive Sign
- Service Drop
- 19. Handrailing
- 20. LED Area Light
- 21. Curb Ramp
- 22. Handicap Parking Space











GC MURPHY BUILDING



WHAT TO DO (EAT)?


- Document what's in the fridge?
- Prioritize what food requires least preparation?
- Assess how much can I really eat?
- Align who will share my table?
- Persist clean your plate, eat again!
- Celebrate have dessert!



SUCCESS STORIES FROM THE FIELD

EMILY WILSON-HAUGER, NEW HISTORIC THOMAS & WOODLANDS DEVELOPMENT GROUP

City of Thomas







Building a Vacant & Dilapidated Building Inventory


2011-2012

- Thomas chosen as pilot community for WV Community Development HUB's Vacant and Dilapidated Building Toolkit
- Partnership established with Woodlands Development Group
- Community meetings held
- AmeriCorps assistance gained
- Volunteers recruited and educated
- Surveys completed
- Inventory built



assessing overall condition

		major	failure
Building Structure	building is not leaning, but foundation is in need of minor repairs	the building is not straight - leans or tilts. the foundation is in need of repair	a complete failure of the structure
Roof / Chimney / Gutters	minor deterioration, improper roof repair. Some mortar missing from chimney; gutters in need of repair	a lot of deterioration, missing material, holes in the roof, or sagging roof. alot of mortar missing from chimney or chimney is leaning	completely missing a roof
Windows / Doors	window frames need replacing or paint is peeling	windows missing, doors missing or rotted	completely missing the majority of win- dows and doors
Porch	seperation of the porch from the building, paint needed	significant deterioration; steps missing, porch sagging, supports holding up porch are rotted	there is no porch where there used to be one
Siding / Paint	some peeling or cracking paint	wood siding is rotting, or vinyl / aluminum siding is falling off or is badly deteriorated	



parcel 63.2, lot 115 spruce street

Tom Dale Tom Dale Rt 1 Box 139A Elk Garden WV, 26292

commercial not occupied



S q u a r e Footage	Tax Class	Date Built	When did it become vacant?	Possible Historical Significance	Construction in Progess?
8000	4	1921	?	old Car	no

Building Frame / Structure	Roof / Chimney / Gutters	Windows / Doors	Siding / P	aint Porch
failure	failure	major	major	NA NA
Health and Safet 3 health concern to potential inhabitant neighboring structures and passersby	Jo- located on a s, throughfare s c- Front or Spruce	major neithervia	escence 3 sble building or structural dition	Blight Concentration 2 four or more porpertie on the same street content on the same street of the same stre

Further Notes
• applied for a 2012 FOCUS grant for Phase I
environmental assessment, did not recieve grant

· owner is wary of working with the City of Thomas

Surveyor Elizabeth Beckerle priority factor

11



- 4

prioritizing properties

the properties are preliminary prioritized based on four factors: Health & Safety, Visibility, Obsolescence, and Blight Concentration. The properties are prioritized on a scale of 1 to 3.

Health & Safety	Visibility	Obsolescence	Blight	Visibility Map
0 not applicable	0 not applicable	0 not applicable	Concentration	
1 poses minimum to	1 located on a side	1 viable building type	0 not applicable	\checkmark
no health concerns to potential inhabitants, neighboring structures,	street majorly frequent- ed by street's residents	use and viable structure condition	1 three or less vacant properties on a single street or intersection	
and passersby	2 located on a through street to a less frequent-	2 either viable building	street of intersection	\frac{\fir}{\fint}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}}{\frac}}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac}}}}}}}}}}}}{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\frac{\fi
2 poses health con- cerns to potential	ed destination such as the Thomas Education	type use or viable struc- ture condition	2 four or more porperties on the same street or	
inhabitants, although not a health concern to neighboring structures	Center or the Buxton Landstreet Building.	3 neither viable Build- ing type use or struc- tural condition	intersection where the average condition of the buildings is fair	12/1
or passersby	3 located on a major	tarar condition	3 (
3 health concern to potential inhabitants, neighboring structures	throughfare such as Front or Spruce streets		3 four or more properties on a street or intersection where the average condition of the properties	
and passersby.			is poor	average visiblity (2)
				most visibility (3)

Blight Concentration Map



hwy 219 blight (2)

Co. Rt.//Front Street blight (2)

Co. Rt. // douglas Rd blight (2)

spruce street /second street blight

third /buxton street blight (3)

Brown St. (3)

ten highest priority properties

parcel 63.2, lot 115 11 spruce street

> Tom Dale Rt 1 Box 139A Elk Garden WV, 26292

parcel 31?, lot 6 douglas road / Co. Rte. 27

> William & Jeanine Hamilton 197 Philips Drive Hampstead, MD 21074

parcel 51, lot 37 spruce street

> **HBK Properties HBK Properties** PO Box 138 6740 Crus Corvi Road Davis, WV 26260 West Jordan UT, 84084

parcel 40, lot 28 spruce street

Carla J Robinette, Frederick Herz & Rose Marie Herz PO Box 672 Davis, WV 26260

parcel 203, lot 169 9 buxton street

> Anthony Lambruno PO Box 275 Thomas, WV 26292











parcel 40, lot 18 douglas road / Co. Rte. 27

> Raymond Collins et. al. 102 Spruce Street Kingwood, WV 26537

parcel 16, lot 35 douglas road / Co. Rte. 27

> Robert Bond Ludwig PO Box 759 Davis, WV 26260

parcel 21 (but JB23?) front street / Co. Rte. 27

9

Michael Thompson 2538 Chesterville Road Mineral Wells, WV 26510

parcel 134 front street / Co. Rte.

Jeffray D & Rebecca J Burns HC 60 Box 30 Thomas, WV

parcel 112, lot C hwy 219

> Emelia Reedy 13423 Justice Road Rockville, MD 20653











10


10

9



New Historic Thomas









1990's

Accomplishments – 1990's

- Re-bricked historic 3rd street
- Removed old railroad ties from the grade
- Improved sidewalk conditions
- Purchased the Western Maryland building
- Acquired a historic commercial district status for downtown Thomas



Mission



New Historic Thomas is a non-profit community group dedicated to revitalizing the city of Thomas by preserving its history, cultural heritage, and resources that make the city unique.

Working with the mayor and city council, New Historic Thomas aims to preserve the city's built and natural environment, businesses, and people so that Thomas continues to be a thriving environment for residents, visitors, and the business community.



NHT Committees:

- Beautification
- Resource
- Redevelopment
- Planning

Other NHT Accomplishments

- Presentations on NHT's work at the 2012 and 2013 WV Brownfields Conferences
- Engineering and design of an 80' pedestrian bridge
- Administration of an \$18,000 grant from the McDonough Foundation to build a restroom at the Tucker County Emergency Shelter located in Thomas
- Fostering a relationship with USFS to partner on development projects.
- Completion of a study of downtown business development needs by Davis and Elkins College

- Purchase and maintenance of flower barrels and benches for the East Avenue commercial district
- Purchase and maintenance of picnic tables for the riverfront rail grade
- Planted and continued maintenance the City Hall Garden
- Pruned apple trees along on East Avenue
- Funded and commissioned local artist to design and construct a trailhead sign • for the Thomas City Park and Trails

- Organize yearly trail maintenance volunteer day for the Thomas City Trails System
- Maintain list of volunteers for as needed tasks and projects
- Application for a \$180,000 DOH Recreational Trails Program Grant (Pending)
- Built handicapped accessible connector trail
- Contributed to the city's holiday decorations with additional lighting on the apple trees
- Secured USDA RCDI Initiative funds to hire a part-time Executive Director (term beginning October 2015)

Partnership w/ Northern Brownfields Assistance Center



Riverfront Park Development Plan







U.S. EPA Brownfields Hazardous Substances Assessment Grant





Redevelopment Progress













Progress -Woodlands Development Group






Progress – Individuals





Progress – Organizations






Inventory Progress

35 properties in the inventory 13 downtown properties

- 1 demolition
- 1 demolition scheduled
- 1 in process of rehabilitation
- 1 partial deconstruction
- 2 redeveloped and back in use
- 1 façade improvement mural



BAD Buildings Program





For more information:

Web: <u>www.newhistoricthomas.com</u>

Email: newhistoricthomas@gmail.com

FB: <u>www.facebook.com/NewHistoricThomas</u>